

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

**Note: Volume V – Traffic Control Devices is now published in three parts.**

**Chapters and binders**

**Before updating the contents:**

- the introductory pages as well as Chapter 1, “General”, Chapter 2, “Regulatory Signs”, and Chapter 3, “Warning Signs”, must be transferred to a new binder, which becomes “Part 1”;
- Chapter 4, “Roadwork Signing”, remains in the current binder, which becomes “Part 2”;
- Chapter 5, “Guide and Information Signs”, Chapter 6, “Pavement Markings”, Chapter 7, “Bikeways”, and Chapter 8, “Traffic Control Signals”, remain in the current “Part 2” binder, which becomes “Part 3”.

**Introductory Pages**

Remove		Insert	
Pages	Date	Pages	Date
—		Note to readers – Evolution of standardization	
Updates list		Updates list	
Half-title and Legal Deposit ( <i>Part 1</i> )		Half-title and Legal Deposit ( <i>Part 1</i> )	
Schedule of deadlines	December 2012	Schedule of deadlines	January 2014
Introduction	December 2012	Introduction	January 2014
Table of Contents i to iii		Table of Contents i to iii	
General Notes 3 to 8	Oct. 2011 Dec. 2012	General Notes 3 to 8	Dec. 2012 Dec. 2013 Jan. 2014
Half-title and Legal Deposit ( <i>Part 2</i> )		Half-title and Legal Deposit ( <i>Part 2</i> )	
Table of Contents i		Table of Contents i to iii ( <i>Part 2</i> )	
—		Half-title and Legal Deposit ( <i>Part 3</i> )	
—		Table of Contents i to iii ( <i>Part 3</i> )	

**Pages in Volume Chapters**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
General	—	—	—	—	This update improved the layout and corrected misprints.  References were updated: L.R.Q. and R.R.Q. were replaced by RLRQ.
Vol. 1	Cover, tab and back		Cover, tab and back		New cover page
1	i and ii	Dec. 2012	i and ii	Jan. 2014	The table of contents was updated.
	1 to 8	Dec. 2004 Dec. 2008 Dec. 2011	1 to 8	Dec. 2004 Jan. 2014	Section 1.3 “Definitions”: a reference to the Highway Safety Code was added for the definition of the word “Bus”.

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
1	11 to 14	Dec. 2010 Dec. 2011	11 to 14	Dec. 2010 Jan. 2014	<p>Section 1.6 “Uniformity of Traffic Control Devices”: a reference to the Québec Traffic Control Devices Directory was added.</p> <p>Section 1.7 “Shapes and Colours of Traffic Signs and Other Control Devices”: clarifications regarding the use of flashing LEDs along the edge of Stop and Yield signs were added.</p> <p>Section 1.9 “Sign Dimensions”: a clarification pertaining to the dimensions of tab signs used with diamond-shaped signs was added.</p> <p>Table 1.9–1: a clarification pertaining to the name of signs was added in note 1 in the French version only.</p> <p>Table 1.9–3: clarification pertaining to the size of tributary, river and bridge signs.</p> <p>Section 1.10 “Pictographs”: text regarding the maximum number of pictographs which may be found on a sign was added.</p> <p>Table 1.10–1: the visual for “X,Y m” sign was modified.</p>
	19	Dec. 2012	19	Jan. 2014	<p>Section 1.14 “Materials for Signs and Delineators”: a reference to <i>Tome III – Ouvrages d’art</i> for the thickness of the sheet metal used in signage was added.</p>
	i to v 1 and 2 7 to 10	Dec. 2012 Dec. 2010 Dec. 2011 Dec. 2005 Dec. 2009 Dec. 2011	i to v 1 and 2 7 to 10	Jan. 2014 Dec. 2010 Jan. 2014 Dec. 2005 Dec. 2011 Jan. 2014	<p>The table of contents was updated.</p> <p>Section 2.1 “Purpose”: the text was harmonized with that of Section 289 of the Highway Safety Code.</p> <p>Section 2.9 “Speed Limit Signs”: signs P-70-3-B, P-70-3-C and P-70-3-D regarding the signing of the speed limit in a school zone were added.</p> <p>Section 2.10.1 “One-Way Traffic Sign”: tab sign P-80-P-1 was introduced to sign two-way bicycle traffic on a one-way street.</p>
2	13 to 26	Dec. 2005 Dec. 2008 Dec. 2009 Dec. 2010 Dec. 2011 Dec. 2012	13 to 26	Dec. 2005 Dec. 2009 Jan. 2014	<p>Section 2.14 “Mandatory or Prohibited Movements at Some Intersections Signs”: the meaning of Except Authorized Vehicles tab sign P-110-P-2 when it is affixed under signs P-110-1 to P-110-8 was clarified.</p> <p>Section 2.15 “Mandatory Route for Particular Classes of Vehicles Signs”: the meaning of the truck outline on signs P-120-12 to P-120-14 was clarified.</p>

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
2	29 to 38	Dec. 2005 April 2009 Dec. 2010 Dec. 2011	29 to 37	Jan. 2014	<p>Section 2.15.2 “Local Delivery Only Sign”: the meaning of the truck outline on sign P-130-24 was clarified.</p> <p>Section 2.16 “Access Prohibited Signs”: the paragraph on the appearance of a maximum of two outlines on a sign was removed.</p> <p>Section 2.18 “Controlled Parking Signs”: the section was restructured.</p> <p>Section 2.21 “Legal Load Limitation Sign”: the term “trucks” was replaced by “vehicles”.</p> <p>Section 2.27 “Reserved Lane Signs”: the term “minibus” was added and the section was restructured to create Sections 2.27.1 “Reserved Lane on Freeways” and 2.27.2 “Reserved Lane in Urban Areas”.</p> <p>Section 2.28.1 “Warrants for the Installation of Crossing Signs”: clarifications regarding the verification of condition No. 3 and of an example of application of this condition were added.</p> <p>Section 2.33 “Use of Engine Brakes Prohibited Sign”: this section was removed.</p>
	SD 001A and SD 001B	Dec. 2005 Dec. 2011	SD 001A and SD 001B	Jan. 2014	<p>SD 001A: Note 1 was added.</p> <p>SD 001B: the distance at which Warning signs must be erected for a speed limit of 40 km/h was added.</p>
	SD 005 to SD 010	Dec. 2005 Dec. 2009	SD 005 to SD 010	Dec. 2005 Jan. 2014	<p>SD 005 to SD 007 and SD 009: the distance at which Warning signs must be erected for a speed limit of 40 km/h was added.</p> <p>Erratum (without modification to the date on the page): SD 010, SD 015 and SD 017: change “special mobile equipment” for “tool vehicle” in the title to agree with the French version.</p>
	SD 015 to SD 020	Dec. 2005	SD 015 to SD 020	Dec. 2005 Jan. 2014	<p>SD 016: two signs were replaced by sign P-130-26.</p> <p>SD 018 and SD 019: the distance at which Warning signs must be erected for a speed limit of 40 km/h was added.</p> <p>SD 016, SD 018 and SD 019: change “special mobile equipment” for “tool vehicle” in the title to agree with the French version.</p>

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
2	SD 023B to SD 030	March 2006 Dec. 2005	SD 023B to SD 030	Dec. 2005 Jan. 2014	SD 024 to SD 028: the distance at which Warning signs must be erected for a speed limit of 40 km/h was added.  SD 024: the title was changed.  SD 029: signing to be installed when cyclists may travel in both directions on a one-way street was added.
	SD 033 to SD 036	Dec. 2005 Dec. 2011	SD 033 to SD 036	Dec. 2005 Jan. 2014	SD 034 and SD 035: the distance at which Warning signs must be erected was corrected.  SD 036: the standardized drawing was removed.
3	i to vi	Dec. 2012	i to vi	Jan. 2014	The table of contents was updated.
	1 to 8	Dec. 2004 Dec. 2005 Dec. 2007 Dec. 2010 Dec. 2012	1 to 8	Dec. 2004 Dec. 2007 Dec. 2010 Jan. 2014	Section 3.1 “Purpose”: the text was harmonized with that of Section 289 of the Highway Safety Code.  Table 3.4–1: the distance at which Warning signs must be erected for a speed limit of 40 km/h was added.  Section 3.8 “New Traffic Control Signs”: a reference to SD 001B concerning the signing of change in speed limit was added.
	11 and 12	Dec. 2004 Dec. 2010	11 and 12	Dec. 2010 Jan. 2014	Section 3.11 “Maximum Speed Ahead Sign”: new maximum speed ahead tab signs were introduced.  Section 3.12 “Two-Way Traffic Ahead Sign”: new signs for two-way bicycle traffic on a one-way street were introduced.
	15 and 16	Dec. 2004 Dec. 2009	15 and 16	Jan. 2014	Section 3.18.1 “Merge Sign” and 3.18.2 “Added Lane Sign”: a clarification regarding the installation of signs D-140-1 and D-140-2 on a service road was added.
	25 and 26	Dec. 2011	25 and 26	Jan. 2014	Section 3.23 “Low Clearance Signs”: a clarification regarding the overhead clearance starting with which signs D-190-1 and D-190-2 must be installed was added.  Section 3.24 “Narrow Passage Sign”: the requirement regarding the usable width of a bridge and of an expertise performed by an engineer when the length of the bridge exceeds 30 m was added.
	25 and 26	Dec. 2011	25 and 26	Dec. 2011 Jan. 2014	Section 3.34.8 “Farm Animals Crossing Sign”: the reference was updated.

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
3	SD 001 to SD 012	Dec. 2005 Dec. 2007 Dec. 2011 Dec. 2012	SD 001A to SD 012	Dec. 2005 Jan. 2014	SD 001A: the title and number were changed. SD 001B: new standardized drawing. SD 002A to SD 011: the distance at which Warning signs must be erected for a speed limit of 40 km/h was added.
	SD 023 to SD 028	Dec. 2005 Dec. 2007 Dec. 2011 Dec. 2012	SD 023 to SD 028	Jan. 2014	SD 023 to SD 028: the distance at which Warning signs must be erected for a speed limit of 40 km/h was added.
Vol. 2	Cover, tab and back		Cover, tab and back		New cover page
4	i to vii  1 and 2	Dec. 2012  Dec. 2011	i to vii  1 and 2	Jan. 2014  Jan. 2014	The table of contents was updated. Section 4.1 “Purpose”: the text was harmonized with that of Section 289 of the Highway Safety Code. Section 4.2 “References”: the reference to Standard CSA Z96 was updated.
	13.1 and 13.2	Dec. 2011	13.1 and 13.2	Dec. 2011 Jan. 2014	Section 4.14.1 “Work Crew Ahead”: the section title and sign name were changed.
	15.2 and 16	Dec. 2012	15.2 and 16	Dec. 2012 Jan. 2014	Section 4.14.13 “Loader”: new section.
	18.2 to 20	Dec. 2006 Dec. 2009 Dec. 2010	18.2 to 20	Dec. 2010 Jan. 2014	Section 4.19.3 “Escort Vehicle”: a clarification regarding the equipment to be installed on an escort vehicle was added, new sign (T-165) and new figure regarding the installation of Traffic with Escort Vehicle sign T-170-5.
	27 and 28	Dec. 2004 Dec. 2012	27 and 28	Dec. 2012 Jan. 2014	Section 4.20.4 “Pedestrian and Bicycle Detour”: new section. Figure 4.34–1: references to Standard CSA Z96 were updated.
	29.2 to 30.3	Dec. 2005 Dec. 2007 Dec. 2012	29.2 to 30.3	Dec. 2005 Dec. 2012 Jan. 2014	Section 4.36.1 “Characteristics”: introduction of lighting strips in the section on 360° beacons.
	37 and 38	Dec. 2012	37.1 to 38	Jan. 2014	Section 4.42.4 “Pedestrian Walkways”: text on the installation of signs to indicate a pedestrian and bicycle detour was added.
	39.3 and 40	Dec. 2012	39.3 and 40	Dec. 2012 Jan. 2014	Section 4.44 “Sign Covers”: the figure number referred to in second paragraph was corrected (French version only). Figure 4.42–3: the position of signs T-100-1-G and T-70-2 was changed in the sequence of traffic signs.

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
4	43 to 48	Dec. 2006 Dec. 2009 Dec. 2010 Dec. 2011 Dec. 2012	43 to 48	Dec. 2011 Jan. 2014	Appendix B: the name of Construction Area signs was changed and a Pedestrian and Bicycle Detour sign and a Loader sign were added.  Appendix B: the Follow this Vehicle sign was added.  Appendix B: lighting strips were added.
	TCD 095 and TCD 096	Dec. 2010	TCD 095 and TCD 096	Dec. 2010 Jan. 2014	TCD 095: the name of the Construction Area sign was changed.
Vol. 3	Cover, tab and back		Cover, tab and back		New cover page
5	i to x 1 to 98	Dec. 2012 All dates	i to xi 1 to 125	Jan. 2014 Jan. 2014	The table of contents was updated.  Section 5.1 “Purpose”: the text was harmonized with that of Section 289 of the Highway Safety Code.  Section 5.2 “References”: references were updated.  Section 5.3 “Definitions”: definitions were updated and “Built-up area”, “Radar” and “Photographic surveillance” were added.  <b>A “Destination / Locator” separator was inserted after page 2.</b>  Section 5.4.1.1 “General Principles”: the name of the section was changed (formerly “Principles”) and content was restructured.  Section 5.4.1.2 “Specific Principles”: new section reusing part of the content of old Section 5.4.1.1 “Principles”.  Section 5.4.1.3 “Destination Selection Method”: <ul style="list-style-type: none"> <li>• renumbering of the section;</li> <li>• restructuring of content;</li> <li>• harmonization of terms used;</li> <li>• graphic improvement.</li> </ul> Section 5.4.1.4 “Major Destinations”: <ul style="list-style-type: none"> <li>• renumbering of the section;</li> <li>• restructuring of content;</li> <li>• addition of a reference to Appendices A to K “Major Destinations on Freeway”.</li> </ul>

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
5					<p>Section 5.4.1.5 “Lakeshore Communities”: the section was renumbered and content was adjusted.</p> <p>Section 5.4.1.6 “Indian Reservations”: new section.</p> <p>Section 5.4.1.7 “Directional Signing Principles”: the section was renumbered and graphic content was improved.</p> <p>Section 5.4.2 “Use of Destination Signs”: the title was changed and the section was renumbered (formerly 5.4.2.1 “Use”).</p> <p>Section 5.4.3 “Types of Destination Signs”:</p> <ul style="list-style-type: none"> <li>• title change and renumbering of the section (formerly 5.4.2.2 “Types of Signs”);</li> <li>• highlighting of sections (for instance: old topic A. “Exit Confirmation Sign” has become 5.4.3.1 “Exit Confirmation Sign”);</li> <li>• restructuring and adjustment of section content;</li> <li>• graphic improvement of signs.</li> </ul> <p>Section 5.4.3.7 “Exit Only Signs”: topics A. “Weaving Zone Less Than 600 m Long” and B. “Weaving Zone 600 m or Longer” were introduced.</p> <p>Section 5.4.3.9 “Last Exit Before Toll”: new section (content taken from point F. “Other Messages” in old Section 5.4.4.1 “Sign Elements”).</p> <p>Section 5.4.3.12 “Destination Direction Signs”: the section was renumbered (old Section 5.4.3.1 “Destination Direction Signs”) and content of old Section 5.4.3.3 “Lakeshore Community Signs” was transferred to point C. “Lakeshore Community Signs”.</p> <p>Section 5.4.3.13 “Destination Distance Sign”: the section was renumbered (formerly Section 5.4.3.2 “Destination Distance sign”).</p> <p>Section 5.4.4 “Destination Sign Design”: an introduction to the section was added and content was reorganized.</p> <p>Section 5.4.4.1 “Small Sign Elements”: new section regrouping the content relating to the design of small signs including old Section 5.4.3 “Description of Other Destination Signs”.</p>

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
5					<p>Section 5.4.4.2 “Oversized Sign Elements”: the title was modified, the section was renumbered (old Section 5.4.4.1 “Sign Elements”) and the figures were adjusted and graphically improved.</p> <p>Section 5.4.4.3 “Layout of Oversized Sign Elements”:</p> <ul style="list-style-type: none"> <li>• title modification and renumbering of the section (formerly Section 5.4.4.2 “Layout of Sign Elements”);</li> <li>• addition of clarifications on the spacing of elements;</li> <li>• graphic adjustment and improvement of figures.</li> </ul> <p>Section 5.4.4.4 “Oversized Sign Dimensions”:</p> <ul style="list-style-type: none"> <li>• title modification and renumbering of the section (formerly Section 5.4.4.3 “Sign Dimensions”);</li> <li>• content adjustment of Table 5.4–9 “Dimensions of elements on a Guide sign”;</li> <li>• graphic improvement of figures.</li> </ul> <p>Section 5.5 “Locator Signs”: sections presenting locator signs were renumbered, content was restructured and signs were adjusted and graphically improved.</p> <p>Section 5.5.1 “Guide Tab Sign”: sections relating to information tab signs were regrouped (old Sections 5.5.7 “Cardinal Direction Tab Signs”, 5.5.9 “Arrow Tab Signs”, 5.5.10 “Distance Tab Signs” and 5.5.11 “Junction Tab Sign”) and sign visuals were added or corrected.</p> <p><b>The “Off-Road Facilities / Information” separator was inserted after page 52.</b></p> <p>Section 5.6 “Off-road Facility Signs”: content of sections presenting off-road facility signs were restructured and adjusted and signs were graphically improved.</p> <p>Section 5.6.3.1 “Airport Signs”: eligibility criteria for major airports were introduced and content was restructured.</p> <p>Section 5.6.4.1 “Park and Ride Signs”: figure 5.6–1 was introduced.</p>



Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
5					<p>Section 5.6.4.4 “Parking Area for Hikers Sign”: new section.</p> <p>Section 5.6.5 “Waste Treatment Site”: new section regrouping Section 5.6.5.1 “Sanitary Landfill Site Sign” and Section 5.6.5.2 “Ecocentre” (new section).</p> <p>Section 5.6.7 “Higher Education Institutions”: new section regrouping Section 5.6.7.1 “University Sign” and Section 5.6.7.2 “CÉGEP Sign” (new section).</p> <p>Section 5.6.8 “Other Facilities”: new section regrouping Section 5.6.8.1 “Public Facilities Signs” and Section 5.6.8.2 “Boat Ramp Sign”.</p> <p>Section 5.6.9 “Border Crossing Sign”: the title Border Crossing sign I-373 was modified (formerly “Customs”) and the associated tab signs were changed.</p> <p>Section 5.7 “Information Signs”: the content of sections presenting the information signs was restructured and adjusted.</p> <p>Section 5.7.4 “Traffic Signal Pushbutton”: new section regrouping Section 5.7.4.1 “Pedestrian or Bicycle Signal Pushbutton Sign” and Section 5.7.4.2 “Diagonal Pedestrian Crossing Sign”.</p> <p>Section 5.7.7 “Emergency Lane Signs”: the name of Emergency Lane sign I-415-2 was changed (formerly “Run-away Lane”).</p> <p>Section 5.7.10 “Exclusive Towing Signs”: content was adjusted according to phrasing of section 12.1.1 of the Act respecting the Ministère des Transports (CQLR, chapter M-28).</p> <p>Section 5.7.14 “Toll”:</p> <ul style="list-style-type: none"> <li>• creation of Section 5.7.14.1 “Toll Systems”;</li> <li>• introduction of Section 5.7.14.2 “Toll Rates Signs” (old Section 5.4.3.4 “Toll Rates”);</li> <li>• addition to Section 5.7.14.2 “Toll Rates Signs” of sign I-422-4 and associated text.</li> </ul> <p>Section 5.7.17 “Transmitter-Receiver Station Sign”: new section.</p>

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
5					<p><b>A “Tourist / Services” separator was inserted after page 79.</b></p> <p>Section 5.8 “Tourist Signs”: the title of the section was changed (formerly “Tourist Facilities Signs”) and content of the sections presenting tourist signs was restructured and adjusted.</p> <p>Section 5.8.1.1 “Roadside Parks”: a new use for sign I-620-2 was added to point E. “Village-Relais Signs”.</p> <p>Section 5.8.1.4 “Tourist Information Offices”: the layout of elements on “Centre Infotouriste” and “Information touristique” signs was corrected.</p> <p>Section 5.8.2 “Heritage Site Signs”: the name and visual of Heritage Site sign I-540 (formerly “Historic Area Sign”) was modified and a clarification regarding the sites involved was added.</p> <p>Section 5.8.5 “Tourist Routes and Circuits”: the section was relocated (formerly 5.5.3.2 “Tourist Route Markers”).</p> <p>Section 5.9 “Fuel and Food Services Signs”:</p> <ul style="list-style-type: none"> <li>• restructuring and adjustment of the content of sections presenting the fuel and food services signs;</li> <li>• replacement of the term “essence” with the term “carburant” in the French version only;</li> <li>• graphic improvement of signs;</li> <li>• adjustment of references to appendices.</li> </ul> <p><b>An “Installation / Appendices” separator was inserted after page 122.</b></p> <p>Section 5.10 “Installation of Guide and Information Signs”: an introduction was added to the section (content of old Section 5.10.2 “Installation of Other Signs”), content of the following sections was restructured and adjusted.</p> <p>Appendices A to K “Major Destinations on Freeways”:</p> <ul style="list-style-type: none"> <li>• new appendices stemming from former SD 039 to SD 085;</li> <li>• restructuring by region;</li> <li>• addition of the Montérégie region;</li> </ul>
	99 to 112	All dates	127 to 191	Jan. 2014	



Update No. 103 of the Collection Normes – Ouvrages routiers

January 2014

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
5	SD 001 to SD 093	All dates	SD 001 to SD 053	Jan. 2014	<ul style="list-style-type: none"> <li>• adjustment of major destinations;</li> <li>• graphic improvement.</li> </ul> <p>Appendix L “Pictographs for Private Tourist Facilities”: the order of the appendix was changed (old Appendix A).</p> <p>Appendices M to Q “Sections of the Freeway System Reserved for the Signing of Major Attractions”: the order of the appendices was changed (old Appendices B to F) and graphics were improved.</p> <p>Appendices R to V “Exclusion Corridors for the Signing of Fuel and Food Services”: the order of the appendices was changed (old Appendices G to K) graphics were improved.</p> <p><b>A “Standardized Drawings” separator was inserted after page 191.</b></p> <p>SD 001 to SD 053:</p> <ul style="list-style-type: none"> <li>• renumbering of standardized drawings according to restructuring of chapter content;</li> <li>• updated signs, tables and notes;</li> <li>• removal of old SD 039 to SD 085 transferred to appendices;</li> <li>• graphic improvement.</li> </ul> <p>SD 017 to SD 020: new standardized drawings dealing with signing of weaving zones.</p> <p>SD 036: new standardized drawing dealing with signing on the approaches to a place that is subject to mobile photo radar device surveillance on a freeway.</p>
6	i to v  1 and 2  7 and 8.1	Dec. 2012  Dec. 2010  Dec. 2011	i to v  1 and 2  7 and 8.1	Jan. 2014  Dec. 2010 Jan. 2014  Dec. 2011 Jan. 2014	<p>The table of contents was updated.</p> <p>Section 6.1 “Purpose”: the text was harmonized with that of Section 289 of the Highway Safety Code.</p> <p>Section 6.10.1 “Stop Lines”: a typo was corrected.</p>
7	i to iv  1 to 6	Dec. 2012  Dec. 2007 Dec. 2009	i to iv  1 to 6	Jan. 2014  Dec. 2007 Jan. 2014	<p>The table of contents was updated.</p> <p>Section 7.1 “Purpose”: the text was harmonized with that of Section 289 of the Highway Safety Code.</p>

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
7	9 to 16	Dec. 2007 Dec. 2010	9 to 16	Dec. 2010 Jan. 2014	<p>Section 7.6.1 “Location of Signs”: references to new standardized drawings were added.</p> <p>Section 7.8.5 “Except Bicycles Tab Sign”: tab sign P-80-P-1 was introduced to sign two-way bicycle traffic on a one-way street.</p> <p>Section 7.8.9 “Access Prohibited Signs”: the term “quad” was replaced by “motoquad” in the French version.</p> <p>Section 7.8.16 “Cyclist Requirement at a Pedestrian Signals Sign”: the visual for Cyclist Requirement at a Pedestrian Signals sign P-285 was changed.</p> <p>Section 7.9.4 “Two-Way Bicycle Traffic on a One-Way Street Ahead Sign”: a new section regarding the signing of two-way bicycle traffic on a one-way street was added and the other sections were renumbered.</p> <p>Section 7.9.9 “Narrow Passage Sign”: tab sign D-200-P-1 was renumbered.</p>
	25 to 30	Dec. 2007 Dec. 2012	25 to 30	Dec. 2007 Dec. 2012 Jan. 2014	<p>Section 7.12 “Pavement Markings”: text on the marking of bicycle paths in exclusive right-of-ways was added.</p> <p>Section 7.12.3.1 “Stop Line”: text regarding the bike box was added.</p> <p>Section 7.12.4.2 “Busy Public Access”: reference to SD 028 was removed from Chapter 7 “Bikeways” and a reference to SD 029 of Chapter 2 “Regulatory Signs” was added.</p> <p>Section 7.12.4.3 “Pavement Symbols”: reference to SD 028 from Chapter 7 “Bikeways” was removed and a reference to SD 029 of Chapter 2 “Regulatory Signs” was added.</p> <p>Erratum (without modification to the date on the page): Table 7.12–2: the first line under Bicycle lane was corrected to agree with the French version.</p>
	35 to 42	Dec. 2007 Dec. 2008 Dec. 2009 Dec. 2010	35 to 42	Dec. 2009 Jan. 2014	<p>Appendix D: the chevron was corrected.</p> <p>Appendix E: the chevron was corrected.</p> <p>Appendix F, 1) Regulatory signs: tab sign P-80-P-1 was added and Sign P-285 was corrected.</p> <p>Appendix F, 2) Warning signs: the number of tab sign D-200-P-1 was corrected.</p>

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
7	SD 025 to SD 028	Dec. 2007	SD 025 to SD 030	Dec. 2007 Jan. 2014	<p>SD 025: the title of the standardized drawing was changed and parking spaces were added on one of the streets to indicate the marking distances of the chevron and bicycle from the edge of the roadway.</p> <p>SD 028: the standardized drawing entitled “Signing for a bicycle lane facing oncoming traffic” was removed.</p> <p>SD 028: new standardized drawing entitled “Signing for a designated roadway facing oncoming traffic”.</p> <p>SD 029: new standardized drawing entitled “Signing for the intersection of a bicycle lane facing oncoming traffic on a one-way street”.</p> <p>SD 030: new standardized drawing entitled “Signing of a bike box at an intersection”.</p>
8	i to ix	Dec. 2011	i to ix	Jan. 2014	The table of contents was updated.
	1 and 2	Dec. 2009 Dec. 2011	1 and 2	Dec. 2009 Jan. 2014	Section 8.1 “Purpose”: the text was harmonized with that of Section 289 of the Highway Safety Code.
	33 and 34	Dec. 2005 Dec. 2009	33 and 34	Dec. 2005 Jan. 2014	Section 8.5.2.8 “Visibility of Signal Heads from Upstream of Intersection”: the reference was updated.
	53 and 54.1	Dec. 2007 Dec. 2011	53 and 54.1	Dec. 2007 Dec. 2014	Section 8.8.2.1 “Shapes, Dimensions and Arrangements of Lenses”: reference to Appendix B was removed and a reference to Appendix A was added.
	63 to 70	Dec. 2009 Dec. 2010 Dec. 2011	63 to 70	Dec. 2009 Dec. 2010 Dec. 2011 Jan. 2014	<p>Table 8.16–1: the minimum height of the display matrix (pixels) for mobile VMS was corrected and Note 3 concerning these VMS was removed.</p> <p>Section 8.16.3.1 “Lettering Characteristics”: a reference to Appendix B dealing with character fonts MTQ 10 × 5 and MTQ 12 × 5 was added.</p> <p>Table 8.16–3: the table values relating to character fonts were adjusted.</p> <p>Figure 8.16–2: the figure was modified to give examples of characters with fonts MTQ 10 × 5 and MTQ 12 × 5.</p>
	73 and 74	Dec. 2010	73 and 74	Dec. 2010 Jan. 2014	Section 8.16.4.3 “Mandatory Expressions”: reference to Appendix A was removed and a reference to Appendix C was added.

Update No. 103 of the Collection Normes – Ouvrages routiers

**January 2014**

**20<sup>th</sup> Update of Volume V – Traffic Control Devices**

Chapter	Remove		Insert		Comments
	Pages	Date	Pages	Date	
8	85 and 86	Dec. 2010	85 to 87	Dec. 2010 Jan. 2014	Section 8.16.4.4 “Pictographs”: reference to Appendix A was removed and a reference to Appendix C was added.
	87 to 90	Dec. 2010 Dec. 2011	89 to 105	Jan. 2014	Section 8.17 “Signs equipped with Flashing LEDs”: new section. Appendix A becomes Appendix C.
	SD 021 and SD 022	Dec. 2005 Dec. 2011	SD 021 and SD 022	Dec. 2005 Jan. 2014	Appendix B: New appendix, character fonts used on VMSs. Appendix C becomes Appendix A and the visual appearance of PMV-T-180 was modified SD 021: graphic improvement.