

Introductory Pages

Remove			Insert	
Page	Date		Page	Date
Half-title and cataloguing data (Part 1 and 2) Half-title and Legal Deposit (Part 1 and 2) Foreword and Note to Users (Part 1) Introduction i to iii (Part 1) Table of Contents v to vii (Part 1) General Notes 5 to 8 (Part 1)	June 1999		Half-title and cataloguing data (Part 1 and 2) Half-title and Legal Deposit (Part 1 and 2) Foreword and Note to Users (Part 1) Introduction i to iii (Part 1) Table of Contents v to vii (Part 1) *General Notes 5 to 8 (Part 1)	June 1999 and July 2000

Chapters and Pages in Volume

Chapter	Remove		Insert		Remarks
	Page	Date	Page	Date	
1	1 to 20	June 1999	1 to 20	June 1999 and July 2000	<p>Section 1.2, a reference was added.</p> <p>Section 1.3, the definitions of “truck”, “local delivery” and “tool vehicle” were changed and definitions for the terms “tow truck”, “tab sign” and “equipment transport vehicle” were added.</p> <p>Section 1.4, the “tab sign” category was removed.</p> <p>*Section 1.7, the term “signal beacon” was replaced by “360° beacon”.</p> <p>Section 1.9, the last paragraph was made compulsory.</p> <p>Table 1.9–1, note d and the dimensions of Alternate Route and Roadwork Period signs were added and the dimensions of Controlled Parking, No Stopping and Detour Via signs were changed.</p> <p>*Table 1.9–3</p> <p>Table 1.9–4, the word “Other” was added in front of municipal facilities and “Highway without services” was moved to Table 1.9–5.</p> <p>*Table 1.9–6, the Local Tourist Information Office signs were split in two.</p> <p>Table 1.9–7, highways with four or more lanes and freeway ramps were added to the types column and the column titles Height and Maximum number were corrected.</p> <p>Table 1.10–1, an advance signal arrow was added.</p> <p>Section 1.10.2, text concerning the truck and its outline was added.</p> <p>Section 1.12.1, text on the fluorescent yellow green and orange coating was added, the term “flexible drum” was added to the list to describe the characteristics of its coating and the Distressed Vehicle Detector sign was added to the list of exceptions.</p>

* This update of Volume V includes amendments to the standard that differ from those of the French version. Users should therefore take note that some pages of the update marked with a star include amendments that were not made to the French version or do not include amendments made to the French version. In all cases, these pages have been republished with the publication date of the French version in order to maintain the correspondence.

Chapters and Pages in Volume

Chapter	Remove		Insert		Remarks
	Page	Date	Page	Date	
1	SD 001 and SD 002	June 1999	SD 001 and SD 002	June 1999 and July 2000	<p>Section 1.13.2, the last sentence of the first paragraph was deleted, being redundant, and the number of the referenced standardized drawing was corrected.</p> <p>Section 1.13.3.1, the authorization to install a Controlled parking sign below 950 mm was rescinded.</p> <p>Section 1.13.4, the third paragraph was moved to section 1.13.3.1.</p> <p>Section 1.15, some terms were corrected.</p> <p>* SD 002</p>
4	1 to 35	June 1999	1 to 43	June 1999 and July 2000	<p>The Table of Contents and some lists were changed to conform to changes in the text.</p> <p>Section 4.3.2, the term “roadwork signal lights” and “signal beacon” was replaced by “roadwork traffic lights” and “360° beacon”.</p> <p>Section 4.4 and Figure 4.4–1, the term “detour lane” was replaced by the term “diversion”, the sign title was corrected and the No Passing sign was added.</p> <p>Section 4.4.2, sub-sections 4.4.2.1 (language of present standard) and 4.4.2.2 (new text on cone markers) were added.</p> <p>Section 4.4.3, the last paragraph was made compulsory.</p> <p>Section 4.4.6, information on retroreflective coating stripes was added.</p> <p>Section 4.5, information on the installation of barricades on the shoulder was added.</p> <p>Sections 4.8, instructions on the installation of signs, delineators and barricades as well as a reference to Chapter 1 were added.</p> <p>Table 4.8–1, the title was corrected.</p> <p>Section 4.10, a major change was made to the text and the sign.</p> <p>Section 4.13.1, the sign title was changed and instructions on removing or covering the sign were added.</p> <p>Section 4.13.3, the sign no longer indicates that work is being carried out up to a maximum height of 5.5 m.</p> <p>Section 4.13.8, a new section on emergency measures signing was added requiring the renumbering of the following section.</p> <p>Section 4.13.9, the use of the tab sign was extended.</p>

* This update of Volume V includes amendments to the standard that differ from those of the French version. Users should therefore take note that some pages of the update marked with a star include amendments that were not made to the French version or do not include amendments made to the French version. In all cases, these pages have been republished with the publication date of the French version in order to maintain the correspondence.

Chapters and Pages in Volume

Chapter	Remove		Insert		Remarks
	Page	Date	Page	Date	
4					<p>Section 4.15 and tables 4.3–1, 4.3–2, 4.4–1, 4.4–2, 4.4–3, 4.8–1, 4.15–1, 4.32–1, 4.36–1 and 4.36–2, the specification “Posted speed limit as per sign with white background” was added.</p> <p>Table 4.15–1, errors were corrected.</p> <p>Section 4.17, the sign T-85-3 was deleted.</p> <p>Section 4.18, information on local delivery only was added.</p> <p>Section 4.19 and figures 4.19–1 to 4.19–3, a major change was made to the text, including the addition of sub-sections 4.19.1 and 4.19.2 (new text on alternate routes) and illustrative figures.</p> <p>Section 4.21, the use of the tab sign was extended.</p> <p>Section 4.31, elements that may appear on sign were added.</p> <p>Sections 4.33.1 to 4.33.3 and Appendix A, the sections were renumbered and the requirement for retroreflective stripes on the sides of the vest was added.</p> <p>Section 4.34, the expression “temporary traffic lights” was replaced by “roadwork traffic lights”.</p> <p>Sections 4.35, 4.36.3, 4.36.6 and 4.40.3, the expression “signal beacon” was replaced by “360° beacon” and sub-section 4.35.1 was added.</p> <p>Section 4.36.1, 4.37 and Figure 4.36–1, the expression “sealed lamp” was replaced by the expression “optical unit”, the features were changed to allow other light sources and the last feature was moved to section 4.36.2.</p> <p>Section 4.36.2, language on the use of signal arrows was added.</p> <p>Section 4.36.6, information on maintenance work in winter was added.</p> <p>Table 4.36–1, requirements relating to pavement marking operations were changed.</p> <p>* Section 4.37 and tables 4.36–1 and 4.36–2, a new section was added, requiring the renumbering of the following sections.</p> <p>Section 4.38 and Appendix C, a new section and an appendix on temporary barriers were added.</p> <p>Section 4.40.6, a reference to Chapter 6 was added.</p> <p>Appendix B, delineators and signs were added, deleted and changed and terms were changed in accordance with changes to text.</p>

* This update of Volume V includes amendments to the standard that differ from those of the French version. Users should therefore take note that some pages of the update marked with a star include amendments that were not made to the French version or do not include amendments made to the French version. In all cases, these pages have been republished with the publication date of the French version in order to maintain the correspondence.

Chapters and Pages in Volume

Chapter	Remove		Insert		Remarks
	Page	Date	Page	Date	
4-TCD	SD 017 and SD 018	June 1999	SD 017 and SD 018	July 2000	SD 017, an error was corrected. SD 018, an error was corrected and signs were replaced.
	SD 027 to SD 036	June 1999	SD 027 to SD 036	June 1999 and July 2000	SD 027 and 028, signs were replaced. SD 029 and 030, errors were corrected and signs were replaced. SD 031 to 033, errors were corrected and the line 80 or 90 km/h in the tables was deleted. SD 034 and 035, the line 80 or 90 km/h in the tables was deleted.
	SD 045 and SD 046	June 1999	SD 045 and SD 046	June 1999 and July 2000	SD 046, signs were replaced.
	SD 079 to SD 084	June 1999	SD 079 to SD 084	June 1999 and July 2000	SD 079, 080, 082 and 083, signs were replaced. SD 084, an arrow was changed.
	SD 089 and SD 090	June 1999	SD 089 and SD 090	June 1999 and July 2000	SD 090, the signal arrow on highways with a posted of speed 90 km/h or over was made compulsory.
4-TLD	SD 001 to SD 081	June 1999	SD 001 to SD 081	July 2000	The Road Work sign and a few other signs were replaced and the delineator table was deleted. SD 008 to 011, 061 and 075, errors were corrected. SD 013 and 014, a note was added. SD 028, the 100 km/h line was added in the table. SD 030, the drawing and sub-title were changed. SD 035 and 036, markings were added. SD 038 to 042, the 80 or 90 km/h line in the tables was deleted. SD 065 to 070, a change was made in the installation of the advance signing described in the notes. SD 068 and 070, the Detour Via sign was replaced.
4-TLDU	SD 015 and SD 016	June 1999	SD 015 and SD 016	June 1999 and July 2000	SD 016, signs were replaced.
	SD 025 to SD 028	June 1999	SD 025 to SD 028	July 2000	SD 025, signs were replaced and errors corrected. SD 026, signs were replaced. SD 027 and 028, signs were replaced and markings corrected.
	SD 043 and SD 044	June 1999	SD 043 and SD 044	June 1999 and July 2000	SD 044, signs were replaced.

Chapters and Pages in Volume

Chapter	Remove		Insert		Remarks
	Page	Date	Page	Date	
7	1 to 26	June 1999	1 to 26	June 1999 and July 2000	<p>Tables and lists were changed in accordance with changes in the text.</p> <p>Section 7.5, a reference was corrected.</p> <p>Section 7.6.1, a reference was corrected.</p> <p>Section 7.6.3.1, information on the height measurement of overhead signs was added.</p> <p>Section 7.8.2, references were added.</p> <p>Section 7.8.3, references were added and two unused signs were deleted.</p> <p>Section 7.8.5, sign P-126 and tab sign P-126-P were combined.</p> <p>Section 7.8.7, 7.9.4 and 7.9.5, a major change was made in the signing for pedestrian and bicycle crossings requiring the renumbering of the following sections.</p> <p>Section 7.8.9, the text was adapted to bikeways.</p> <p>Section 7.9.3, errors were corrected.</p> <p>Section 7.9.6, the title of the sign was changed.</p> <p>Section 7.9.8, information and references were added.</p> <p>Section 7.9.9, a reference was added.</p> <p>Section 7.10.2, the graphics of signs T-90-7, T-90-8-G and T-90-8-D was changed.</p> <p>Section 7.11.4, references were added and errors corrected.</p> <p>Figure 7.11–3, a note was added.</p> <p>Section 7.11.10, information on the pictographs was added.</p> <p>Section 7.11.12 and Appendix F, a new section on border signing was added.</p> <p>Section 7.12.1, a reference error was corrected.</p> <p>Section 7.12.2.1 and 7.12.4.2, the title of the sign was changed.</p> <p>Section 7.12.2.2, information on the colour of the line was added.</p> <p>Section 7.12.2.5, a reference was added.</p> <p>Section 7.12.3.2 and Appendix A, information on a reference was added and the characteristics of the marking of crossings on public highways where the traffic is not controlled were changed.</p> <p>Section 7.12.4.1, the section was rewritten to make it more explicit.</p> <p>Table 7.12–2, errors were corrected.</p> <p>Appendix A, a note was added.</p> <p>Appendix B, errors in dimensions were corrected.</p>

Chapters and Pages in Volume

Chapter	Remove		Insert		Remarks
	Page	Date	Page	Date	
7	29 to 41	June 1999	29 to 40	July 2000	Appendix E, the sequence voided lozenge-bicycle-pedestrian-arrow sequence was added. * Appendix F, new formatting including corrections to the signs mentioned earlier; two unused signs were deleted and a note was added.
	SD 001 and SD 002	June 1999	SD 001 and SD 002	June 1999 and July 2000	SD 002, the crossing signing was changed.
	SD 005 to SD 027	June 1999	SD 005 to SD 027	June 1999 and July 2000	SD 005 to 007, 009 to 022 and 027, the crossing signing was changed. SD 009, a note was changed. SD 010 and 012, errors were corrected. SD 014, the markings were changed. SD 015, the title of the drawing was changed. SD 016, a sign was added and the colour of the voided lozenge was corrected. SD 017, errors were corrected. SD 019 and 020, the markings were corrected. SD 022, a note was corrected. SD 024 and 025, the markings were corrected. SD 026, the values of D in the table were corrected.

* This update of Volume V includes amendments to the standard that differ from those of the French version. Users should therefore take note that some pages of the update marked with a star include amendments that were not made to the French version or do not include amendments made to the French version. In all cases, these pages have been republished with the publication date of the French version in order to maintain the correspondence.